CERTIFICATE No. 09742

SERVICE CERTIFICATE

Hutton Fire Protection Ltd.

Tel: 01429 260 413



INVOICE ADDRESS

SAME AS COCATION

LOCATION ADDRESS				
BELIEVE HO	HOUSE NSING			
SPECTRUM	4			
SPREZTRUM	BUSINESS			
	PARL			
SEAHAM				

NIEVAL

Invoice No
Delivery/Service 9/12
Customer Corder No. 1000/7756

QTY

SPARE PARTS FITTED

HEADCAP ASSEMBLY HEADCAP SEAL

DESCRIPTION	SERVICED	CON'D	RECHARGED	O/A	PTR	O/A	EQUIP	O/A
WATER 9L	:							
FOAM AFFF 1L								
FOAM AFFF 2L				-				
FOAM AFFF 3L								
FOAM AFFF 6L	10							
FOAM AFFF 9L								
CO ₂ 2kg	10							
CO₂5kg								
CO₂ OTHER								
POWDER 1KG							0	
POWDER 2KG								
POWDER 4KG	ia sa							
POWDER 6KG					P			
POWDER 9KG								
POWDER 12KG								
6LTR CLASS F								
3LTR WATER ADDITIVE	-							
6LTR WATER ADDITIVE	2							
7								
		92						
TOTAL EXTINGUISHERS	20			79				
TOTAL HOSE REELS								
TOTAL FIRE BLANKETS								
ENGINEERS COMMENTS	3							
Come			7			/		
						7		
7								
77								
#61/ma _{nj}	ile.							
S								
100,40								
6								
	1 1 0	//	0 1 1			-		-

HOSE/NOZZLE SEAL	10
SAFETY CLIP/PIN	
VALVE ASSY (CO2)	
HORN ASSY (CO2)	
HOSE & HORN ASSY CO2	
TAMPER INDICATOR	20
GAUGE TEST	_
BURSTING DISC	
HOSE REEL NOZZLE	
WORM DRIVE CLIP	
CARTRIDGE 55GM	
CARTRIDGE 75GM	
CARTRIDGE OTHER	
WALL BRACKET	7
EXTINGUISHER ID SIGN	
MISC. O. RINGS 6	10
	14
EXTINGUISHER TESTED	*
BY DISCHARGE	x +
ATTENDANCE FEE	
CALL OUT FEE	
DELIVERY CHARGE	
LABOUR	

Engineer's Signature	
Customer's Signature	Print Name W Contout
Position	Date Signed

TOTAL VAT TOTAL

Fire Extinguisher Service Provider (SP101)

CALL OL

SERVICE

Customer Copy: White A/C: Blue

Inspection by the user: It is recommended that regular visual inspections of all extinguishers be carried out by the user or by user's representative. The frequency of inspections by the user should be not less than monthly and, when circumstances require, inspections should be carried out more frequently. Apart from the non confirming extinguishers as recorded, all portable fire extinguishers have been inspected and serviced in accordance with BS503 PT9 and BS5306 Part 3. Terms Subject to HUTTON FIRE PROTECTION Standard published conditions of sale, applicable to the goods or services described above. Copy available on request.