DURHAM COUNTY COUNCIL

PASSENGER MAINTENANCE REPORT AND SERVICE SHEET

Property Helpdesk contact 03000 267890

Passenger

REF No: 27/19810
ID No: 16380
PROJECT: 1545229

Name: Catherine Crawford
Address:
Park Avenue Close
Crook
DL15 9JR
Telephone No: 01917437390
Client: Believe Housing 2PARA1_Ext_C

Make: Schindler Traction
Type: Passenger (Traction)
Serial No: 10524118-1
Location: Stairwell Left Hand side
No. of floors: 5

Completed: General + Machine Room **Next Service: General + Car**

REQUIRED (NEEDS)

General - Other General: refuge sign for car top and pit (JOB IN HAND)

ALL OTHER COMPONENTS CHECKED ARE SATISFACTORY (NO FAULTS TO REPORT)

After completing the relevant checks the lifting equipment was left in a safe working order

Engineer: Rhys Belshaw

Customer: Customer unavailable to sign off
Date: 15 Jun 2026 15:19

General - Floor Levels	ok	
General - Car Lighting	ok	
General - Car Buttons	ok	
General - Landing Buttons	ok	
General - Alarm	ok	
General - Auto-dialler	ok	
General - Shaft Lighting	ok	
General - Landing Door Locks	ok	
General - Cleanliness	ok	
General - Ride Quality	ok	
General - Other General	fault	refuge sign for car top and pit (JOB IN
		HAND) [Required (needs)]
Machine Room - Machine Room Door	ok	
Machine Room - Signage	ok	
Machine Room - Lighting	ok	
Machine Room - Electrical Connections	ok	
Machine Room - Panel	ok	
Machine Room - Wiring Diagrams	ok	
Machine Room - Stop Switches	n/a	
Machine Room - Motor / Gearbox	ok	
Machine Room - Sheaves	ok	
Machine Room - Brake	ok	
Other - Not Mentioned Above	n/a	