DURHAM COUNTY COUNCIL

PASSENGER MAINTENANCE REPORT AND SERVICE SHEET

Property Helpdesk contact 03000 267890

Passenger

REF No: 27/19815
ID No: 16379
PROJECT: 1545229

Name: Pamela Wilson
Address:
Park Avenue Close
Crook
DL15 9JR
Telephone No: 0191 3497716
Client: Believe Housing 2PARA1_Ext_C

Make: Schindler Traction
Type: Passenger (Traction)
Serial No: 10524118
Location: Stairwell Right Hand side
No. of floors: 5

Completed: General + Machine Room **Next Service: General + Car**

REQUIRED (NEEDS)

General - Other General: safe refuge signs for car top and pit (JOB IN HAND)
Other - Not Mentioned Above: GF landing door closing buffer bent (Part has been ordered)

ALL OTHER COMPONENTS CHECKED ARE SATISFACTORY (NO FAULTS TO REPORT)

After completing the relevant checks the lifting equipment was left in a safe working order

Engineer: Rhys Belshaw

Customer: Customer unavailable to sign off
Date: 15 Jun 2026 16:30

General - Floor Levels	ok	
General - Car Lighting	ok	
General - Car Buttons	ok	
General - Landing Buttons	ok	
General - Alarm	ok	
General - Auto-dialler	ok	
General - Shaft Lighting	ok	
General - Landing Door Locks	ok	
General - Cleanliness	ok	
General - Ride Quality	ok	
General - Other General	fault	safe refuge signs for car top and pit
		(JOB IN HAND) [Required (needs)]
Machine Room - Machine Room Door	ok	
Machine Room - Signage	ok	
Machine Room - Lighting	ok	
Machine Room - Electrical Connections	ok	
Machine Room - Panel	ok	
Machine Room - Wiring Diagrams	ok	
Machine Room - Stop Switches	n/a	
Machine Room - Motor / Gearbox	ok	
Machine Room - Sheaves	ok	
Machine Room - Brake	ok	
Other - Not Mentioned Above	fault	GF landing door closing buffer bent
		(Part has been ordered) [Required
		(needs)]